



Flood Protection





Flood of 1966





Chinook in Santa Rosa Creek






Stormwater Conveyance





Extreme Weather





Vegetation Management 1997



Santa Rosa Creek



Vegetation Management 2007



Santa Rosa Creek




Ludwigia





Lake Mendocino - October 2002

Integrated Regional Water Management



Watershed Management

- Reduced Siltation
- Water Quality
- Habitat

Dam Rehabilitation

- Flood Protection
- Water Supply
- Fish Passage

Land Use Planning

 Protect Groundwater Recharge Areas

Recharge Basins

- Water Supply & Quality
- Pumping Lifts

Water Conservation

Reduced demand

